



MONROE COUNTY
FLORIDA



Harry Harris Resilient Redesign

What are the Solutions?

1. Zone 1 – Reinforce existing jetty / walkway and provide dredging within swim area for improved storage and flushing
2. Zones 2, 3, 4, and 5 – Elevate boat ramp and add floating dock, living shoreline (oyster bags, rock riprap, mangroves), tideflex valve, water control structure, rain garden, stormwater / king tide flooding pond
3. Zone 6, 7, and 8 - Boardwalk with shoreline stabilization (SeaHex, WADs, oyster bags, rock riprap, mangroves), rain garden, pervious pavement driveway

